

Printout of prices from the TEILE.PL web side

| Number | 904-00 Windscreen wipers, rain sensor | Year | Cond. | RRP Euro | Disc. | Price Euro |
|-------------|---------------------------------------|-------|-------|----------|-------|------------|
| 99661511300 | Control unit of rain sensor | 98-05 | new | 127.69 | 15% | 108.54 |
| 99762802700 | Wiper arm, L | 98-05 | new | 52.72 | 15% | 44.82 |
| 99762802700 | Wiper arm, L | 98-05 | used | 52.72 | 50% | 26.36 |
| 99762802900 | Wiper arm, R | 98-05 | new | 52.72 | 15% | 44.82 |
| 99762802900 | Wiper arm, R | 98-05 | used | 52.72 | 50% | 26.36 |
| 99662890108 | Wiper blade set, L+R | 98-05 | new | 40.78 | 10% | 36.70 |
| 99662890108 | Wiper blade set, L+R | 98-05 | used | 40.78 | 50% | 20.40 |
| 99762823501 | Wiper linkage | 98-05 | used | 245.54 | 50% | 122.77 |
| 99762823501 | Wiper linkage | 98-05 | new | 245.54 | 15% | 208.71 |
| 99762410501 | Wiper motor | 98-05 | new | 276.15 | 15% | 234.73 |
| 99762410501 | Wiper motor | 98-05 | used | 276.15 | 50% | 138.08 |

| Number | 904-06 Rear screen wipers | Year | Cond. | RRP Euro | Disc. | Price Euro |
|-------------|-------------------------------------|-------|-------|----------|-------|------------|
| 99662804000 | Rear wiper arm, Coupé | 98-05 | new | 177.19 | 15% | 150.62 |
| 94462812200 | Rear wiper cap | 98-05 | new | 4.80 | 15% | 4.08 |
| 99662805000 | Wiper arm, Targa | 98-05 | new | 55.86 | 15% | 47.48 |
| 99662804500 | Wiper blade, rear part, Coupe/Targa | 98-05 | new | 27.86 | 10% | 25.07 |
| 99662808000 | Wiper motor | 98-05 | new | 544.13 | 15% | 462.51 |
| 99662808000 | Wiper motor | 98-05 | used | 544.13 | 50% | 272.07 |
| 99662808001 | Wiper motor, 4S, Turbo | 98-05 | new | 544.13 | 15% | 462.51 |
| 99662809000 | Wiper motor, Targa | 98-05 | new | 562.86 | 15% | 478.43 |

| Number | 904-10 Windscreen washer system | Year | Cond. | RRP Euro | Disc. | Price Euro |
|-------------|--------------------------------------|-------|-------|----------|--------|------------|
| 99662810200 | T-piece | 98-05 | used | 8.00 | 50% | 4.00 |
| 99662810200 | T-piece | 98-05 | new | 8.00 | 15% | 6.79 |
| 99662807703 | Washer nozzle, L=R | 98-05 | used | 15.64 | -1085% | 185.28 |
| 99662807703 | Washer nozzle, L=R | 98-05 | new | 15.64 | -1914% | 314.98 |
| 99652870101 | Water supply tank | 98-05 | used | 92.06 | 50% | 46.03 |
| 99652870101 | Water supply tank | 98-05 | new | 92.06 | 15% | 78.25 |
| 99652870100 | Water supply tank, headlight nozzles | 98-05 | new | 92.06 | 15% | 78.25 |
| 99652870100 | Water supply tank, headlight nozzles | 98-05 | used | 92.06 | 50% | 46.03 |
| 99662817200 | Windscreen washer pump | 98-05 | new | 37.25 | 15% | 31.67 |
| 99662817200 | Windscreen washer pump | 98-05 | used | 37.25 | 50% | 18.62 |

| Number | 904-21 Headlight washer system | Year | Cond. | RRP Euro | Disc. | Price Euro |
|-------------|---------------------------------------|-------|-------|----------|-------|------------|
| 99662816000 | Distributor | 01-05 | new | 67.75 | 15% | 57.58 |
| 00004490064 | Headlight washer system, retrofit kit | 98-01 | new | 562.41 | | 562.41 |
| 99662450200 | Pump | 98-01 | new | 50.71 | 15% | 43.10 |
| 99662450200 | Pump | 98-01 | used | 50.71 | 50% | 25.36 |
| 99662833300 | Washer nozzle, L | 98-01 | used | 161.21 | 50% | 80.61 |
| 99662833300 | Washer nozzle, L | 98-01 | new | 161.21 | 15% | 137.03 |
| 99662833400 | Washer nozzle, R | 98-01 | new | 161.21 | 15% | 137.03 |
| 99662833400 | Washer nozzle, R | 98-01 | used | 161.21 | 50% | 80.61 |

| Number | 904-21 Headlight washer system, facelift 02- | Year | Cond. | RRP Euro | Disc. | Price Euro |
|-------------|--|-------|-------|----------|-------|------------|
| 99662813500 | Pipeline, L | 02-05 | new | 67.75 | 15% | 57.58 |
| 99662813601 | Pipeline, R | 02-05 | new | 67.75 | 15% | 57.58 |